


1/4







2/4






FIG._4





3/4

1/16*	1	2	1
	2	4	2
	1	2	1

FIG._7





FIG._8



4/4




FIG._10

FIG._11A

Fe 0: 0th Line in 1st Field
Fo 0: 0th Line in 2nd Field
Fe 1: 1th Line in 1st Field
Fo 1: 1th Line in 2nd Field

FIG._11B

X _{i-1, j-1}	X _{i-1, j}	X _{i-1, j+1}
X _{i, j-1}	X _{i, j}	X _{i, j+1}
X _{i+1, j-1}	X _{i+1, j}	X _{i+1, j+1}

X Either All From Fe or All From Fo